



Production Model Honing Plate Instructions

Tips For Best Results Using A BHJ Production Model (PM) Honing Plate

1. Do not use a gasket.
2. Always use washers under the bolt heads.
3. Always use the bolts supplied with the Honing Plate.
4. Replace the bolts before the threads deform and cause block thread damage.

The foregoing is intended as a basic guideline. It should not be considered as criteria for a perfect result. Each and every Honing Plate user has their own method and the above tips should be adjusted accordingly.